



1. Plug-in phase terminal 36kV, 630A
2. Plug-in neutral terminal 36kV, 630A
3. Rated plate
4. Earthing terminal
5. Lugs for lifting active part of reactor
6. Filling tube
7. Oil drain valve
8. Tap changer
9. Integrated Safety Detector R.I.S.
10. Hooks for reactor lifting
11. PT100 probe pocket

kVAr	A	B	C	d	e	g	l	m	k		n		Mass(kg)	
									H.V.	L.V.	H.V.	L.V.	Oil	Total
3000	2370	1255	2360	-	1070	-	-	-	275	-	129	-	1650	7030