



1. Plug-in phase terminal 36kV, 630A
2. Plug-in neutral terminal 36kV, 630A
3. Rated plate
4. Earthing terminal
5. Lugs for lifting active part of reactor
6. Filling tube
7. Oil drain valve
8. Tap changer
9. Integrated Safety Detector R.I.S.
10. Hooks for reactor lifting
11. PT100 probe

kVAr	A	B	C	d	e	g	l	m	k		n		Mass(kg)	
									H.V.	L.V.	H.V.	L.V.	Oil	Total
2000	2048	1165	2190	-	1070	-	-	-	275	-	129	-	1535	5875